

10Z
4351


Toyota RAV4 Modell 2013

Oval side bar 90 x 45 mm with dots
Flankenschutzrohr 90 x 45 mm oval mit Noppen
Barre latérale ovale 90 x 45 mm avec des points



ASSEMBLY INSTRUCTION

Montageanleitung • Instructions de montage




45 Minuten

Artikel-Nr:
10Z4351 stainless steel
10Z5351 black steel

Revision 1: 21.05.2013

13
17



1

**10Z4351.1 R /
10Z4351.2 L**

1x



| | | | |
|----------|--|--------------------|-----------|
| a | | M8x20; DIN 933 A2 | 4x |
| b | | M10; DIN 934 Zn | 4x |
| c | | Ø 8,4; DIN 9021 A2 | 4x |
| d | | Ø 10,5; DIN 125 Zn | 4x |
| e | | Ø 8; DIN 127 A2 | 4x |
| f | | Ø 10; DIN 127 Zn | 4x |

2

10Z5154

2x



3

10Z5150

2x



4

10T5132

4x



